



# Oscar Recliner with 2 motors

## Construction:

Frame – metal construction



Seat cushion – not loose, foam HR 35



Back cushion – not loose, foam EP 25



## Upholstery:

Fabric – large range in different price groups



## Leather/PVC

Products in leather might have different sewing than fabric



## Mechanism



Motor  
with lift-up

## Leg



Metal – black

